

Table with columns for device models (BT110, BT220, BT330, etc.) and connection status (O, X, -) for various phone models (BT100, BT200, BT300, etc.).

Table with columns for device models (BT110, BT220, BT330, etc.) and connection status (O, X, -) for various phone models (BT100, BT200, BT300, etc.), including a section for BT100 models.

Table with columns for device models (BT110, BT220, BT330, etc.) and connection status (O, X, -) for various phone models (BT100, BT200, BT300, etc.), including a section for BT100 models.

1/247

Table with columns for device models (BT110, BT220, BT330, etc.) and connection status (O, X, -) for various phone models (BT100, BT200, BT300, etc.).

Table with columns for device models (BT110, BT220, BT330, etc.) and connection status (O, X, -) for various phone models (BT100, BT200, BT300, etc.).

Table with columns for device models (BT110, BT220, BT330, etc.) and connection status (O, X, -) for various phone models (BT100, BT200, BT300, etc.).

Table with columns for device models (BT110, BT220, BT330, etc.) and connection status (O, X, -) for various phone models (BT100, BT200, BT300, etc.).

Table with columns for device models (BT110, BT220, BT330, etc.) and connection status (O, X, -) for various phone models (BT100, BT200, BT300, etc.).

(注) O・・・使用可 X・・・使用不可 -・・・未検証

※1 特種電話機が失効した上を発生させた後、通常のBluetooth®接続を再開した際にBT100の通知音が再生されず、接続も正常にできません。Bluetooth®接続を再開せずに30秒を待機し、再接続を試みてください。

※2 S10専用機は音声を再生することができません。ヘッドセットモードは、通話中に再生する音声を再生し、ヘッドセットモードに入ると音声を再生することができません。再度接続には再接続を待機してヘッドセットモードを使用してください。

※3 BT125はA2DPが入っていませんのでS10の再生は有線になります。

※4 ペアリング・接続も正常にできませんが、ご使用の環境により、通話中に再生する音声が再生しにくく、再生しない場合があります。

※5 ご使用の環境により、通話中に再生する音声が小さい場合があります。マイク・スピーカーの動作により、再生音声が再生しにくくなる場合があります。

※6 特種電話機A2DPが搭載されていないため、ステレオ音声を再生することはできません。特種電話機はモノラルのみとなります。

※7 ヘッドセット及び携帯電話の電源OFF/ONによる再接続時は、携帯電話の電源のOFF/ONを一旦OFFにして再接続から再接続を行ってください。

※ 特種電話機は100MHz帯域であるS10S7-770774を前提としておりません。S10S7-770774帯域にも対応する場合があります。

※ BT125はA2DPが入っていませんのでS10の再生は有線になります。

※ ペアリング・接続も正常にできませんが、ご使用の環境により、通話中に再生する音声が再生しにくく、再生しない場合があります。

※ ご使用の環境により、通話中に再生する音声が小さい場合があります。マイク・スピーカーの動作により、再生音声が再生しにくくなる場合があります。

※ 特種電話機A2DPが搭載されていないため、ステレオ音声を再生することはできません。特種電話機はモノラルのみとなります。

※ ヘッドセット及び携帯電話の電源OFF/ONによる再接続時は、携帯電話の電源のOFF/ONを一旦OFFにして再接続から再接続を行ってください。